



























# HeliosIP

## 2N Helios IP interoperability

PBX	Tested version	Company
Broadsoft	version R17.0	
Innovaphone	version 8	
Asterisk	1.4.18.1	
Elastix	firmware 1.6/12	
Alcatel - Lucent OmniPCXOffice	version 5, 6	
Alcatel - Lucent OmniPCXEnterprise	R9.0 h130142	
CISCO Call Manager	version 6, 7 and 8	
3CX	all versions	
SwyxWare	all versions	
2N® NetStar	all versions	
2N® Omega	all versions	
2N® Omega Lite	all versions	
Telephones	Tested version	Company
SNOM	820, 870	
Grandstream	GXV3000 & GXV 3140 - firmware 1.6.1, hardware 535v1	
Innovaphone	hardware 530v2, firmware 0.0.80	
Yealink	VP-2009	
Polycom	VVX 1500	
CISCO IP phone	9951	
Softphones	Tested version	Company
Couterpath Bria	2.4	
X-Lite	all versions	
SJ Phone	1.65	
Pangolin	4.5 -5.3	
3CX	all versions	
eyeBeam	1.5	
SwyxIt!	all versions	
VoIP Gateways	Tested version	Company
2N® VoiceBlue Next	all versions	
2N® Office Route	all versions	